PRODUCTS: D101GGC (Standard BIOS)

BIOS Version 0313

About This BIOS:
- September 15, 2006
- GC11010N.86A.0313.2006.0915.1840
- Realtek* RTL8139(X)/8130/810X PCI Fast Ethernet MLID v3.64 (010816)

New Fixes/Features:
- Fixed issue where changes to HDD parameters would not save if HDD access mode is set to 'CHS'.
- Fixed incorrect system memory size if an add-on display card is installed.
- Fixed sporadic PS/2 keyboard loss.

BIOS Version 0312

About This BIOS:
- June 09, 2006
- GC11010N.86A.0312.2006.0609.1700
- Realtek* RTL8139(X)/8130/810X PCI Fast Ethernet MLID v3.64

New Fixes/Features:
- Fixed Burn-In test software failure when EIST is enabled.
- Fixed issue where legacy floppy fails after S3 resume.
- Fixed reboot issue with certain memory modules.
- Fixed issue where PCIEx1 LAN cards cannot connect to DHCP server.

BIOS Version 0307

About This BIOS:
- March 16, 2006
- GC11010N.86A.0307.2006.0316.2038
- Realtek* RTL8139(X)/8130/810X PCI Fast Ethernet MLID v3.64 (010816)

New Fixes/Features:
- Add Halt On item and set default value to "All, but keyboard".
- Update Intel full screen logo.
- Update OSB Spec to v3.31.
- Support Modify OSB logo position.

BIOS Version 0306

About This BIOS:
- February 10, 2006
- GC11010N.86A.0306.2006.0210.1125
- Realtek* RTL8139(X)/8130/810X PCI Fast Ethernet MLID v3.64 (010816)

New Fixes/Features:

*Other names and brands may be claimed as the property of others.

- Reserve IRQ 12 to fix boot from lan to Novell server fail.
- Fixed bad Dram SPD can't enter setup menu.
- Fixed Front Fan and Rear Fan show incorrect.
- Fixed second-level page of Boot Menu the "F9 " Key lost function.
- Fixed certain USB flash drive halt on 52h issue.
- Fixed HCT ACPI verify test aging HDD abnormal reboot.
- Updated processor support.
- Set ACPI suspend type S3 State support S1 and S3.

```
BIOS Version 0305
```

About This BIOS:
- December 12, 2005
- GC11010N.86A.0305.2005.1212.1555
- Realtek* RTL8139(X)/8130/810X PCI Fast Ethernet MLID v3.64 (010816)

New Fixes/Features:
- Fixed when after MFG mode and aging suspend S4.System cannot boot to OS normally.
- Add program clock gen code for hardware request.
- Fixed run modbin6 stack overflow.
- Updated processor support.
- Fixed press any key will issue IRQ1 two times when USB controller disable.
- Fixed DDR un-support CAS Latency 4 clocks.
- Support show each DRAM info in memory configuration group.
- Modify Wake on LAN from S5 Item value to "Stay off" and "Power on".
- Follow Intel BIOS spec1.0 show HDD info in Drive Configuration.
- Reorder Advanced screen each group order.
- Support switch logo to text feature by pressing TAB key.
- Modify ACPI Suspend State item value to "S1 State" and "S3 State".
- Modify Memory Configuration Group item string.
- Follow Intel BIOS spec modify hardware monitor string and order.
- Fixed OSB logo color error on ATI VGA card.

```
BIOS Version 0304
```

About This BIOS:
- November 08, 2005
- GC11010N.86A.0304.2005.1108.2115
- Realtek* RTL8139(X)/8130/810X PCI Fast Ethernet MLID v3.64 (010816)

New Fixes/Features:
- Modified some item locations.
- Created USB and Boot configuration group.
- Fixed USB Port3 abnormal.
- Added support for Wake on LAN from S5.
- Modified USB device bootable item string.
- Moved C1E item in Maintence group and modified item string.
- Added support for USB zip emulation type.
- Added Processor stepping, Microcode Revision, Ratio Actual Value Board ID in Maintenance group.
- Added support for maximum multiplier.

```
BIOS Version 0302
```

About This BIOS:

*Other names and brands may be claimed as the property of others.

- October 28, 2005
- GC11010N.86A.0302.2005.1028.1225
- Realtek* RTL8139(X)/8130/810X PCI Fast Ethernet MLID v3.64 (010816)

New Fixes/Features:
- Initial production bios release

LEGAL INFORMATION

Information in this document is provided in connection with Intel Products and for the purpose of supporting Intel developed server/desktop boards and systems.

No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel Corporation may have patents or pending patent applications, trademarks, copyrights, or other intellectual property rights that relate to the presented subject matter. The furnishing of documents and other materials and information does not provide any license, express or implied, by estoppel or otherwise, to any such patents, trademarks, copyrights, or other intellectual property rights. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Intel is a registered trademark of Intel Corporation.
Copyright (c) 2006 Intel Corporation.

*Other names and brands may be claimed as the property of others.